Attachment No. 5 – Final Walkthrough Punch List/ Inspection Report



FINAL WALKTHROUGH PUNCH LIST

		THERE WALK	I HROUGH PUNCH LIST			
				Project		
	Project Name		Project Address	Number	Project Manager	Date
	Jefferson St. WTP Chlorine Feed Improve	ments	2519 Jefferson St.	210163.001	James Hoelscher,P.E.	3/14/2024
serierson st. with emornie recumprovements			2313 3611613011 36.	210103.001	Junies Hoeisener,i .E.	3/ 14/ 2024
14						
Item						
Number	Description	Location		Action Item		Status
	Testing: Pressure Testing for pipes and Density Testing					
1						
_						
	Flowable Fill Placement					
2						
	ARV and Isolation Valves Functionality					
	ANY and isolation valves runctionality					
3						
	n:					
	Piping Connections					
4						
	Wall Penetrations at Flash Mix Building, Chlorine Room, and					
	Filter Building					
_						
5						
	City concurrence of system functionality				·	
6						
			I.			

CITY OF LAREDO UTILITIES DEPARTMENT JEFFERSON ST. WTP CHLORINE FEED IMPROVEMENTS FINAL WALKTHROUGH



Photo Report

DATE: March 14, 2024

CLIENT: City of Laredo Utilities Department

CONTRACTOR: J.S. Haren ENGINEER: Ardurra

ATTENDANCE: Orencio Zamarripa (Ardurra), James Hoelscher (Ardurra),

Al Martinez (Laredo), Mitchell Kouthy (J.S. Haren)

General Punchlist Items

City has moved the ARV provided for the project to just outside the chlorine room. J.S. Haren
has provided cut sheet to Laredo to buy and install one themselves at high point as designed
in project.



Photo 1: Pipes outside of the chlorine room.





Punchlist Items

- Insulate all above ground piping per drawing note.
 - Note: pre-construction photos show point riser at raw water injection entirely insulated before this project. Contractor to re-apply insulation to existing piping as well as new piping.



Photo 2: City, Ardurra, and J.S. Haren discussing outside piping connection at the chlorine room.







Photo 3: 3" Tee and reducer location, south view. (Refer to punch list item 3)



Photo 4: 3" Tee and reducer location, north view. (Refer to punch list item 3)







Photo 5: View of point riser. (Refer to punch list item 3)



Photo 6: Point riser. (Refer to punch list item 3)







PHOTO B: INJECTION POINT RISER

<u>Photo 7</u>: Excerpt from Drawing Package Showing Piping At Raw Water Injection with Insulation Pre-Construction







<u>Photo 8</u>: Contractor to replace sidewalk pavement at chemical building that was removed during construction (Refer to punch list item 4)



Photo 9: Sidewalk outside chemical building. (Refer to punch list item 4)







Photo 10: Line connection to chemical building, east view. (Refer to punch list item 3)




Photo 11: Line connection inside filters building ground level. (Refer to punch list item 5)







Photo 12: Line connection inside filters building lower level. (Refer to punch list item 5)





<u>Photos 13 and 14</u>: Contractor to provide labels/stickers for chemical piping inside filter building to City for placement. (Refer to punch list item 5)







Photos 15 & 16: Tank connection. (Refer to punch list item 5)

