

SCOPE WORK

On #516 Flores St.

1.-ON THE MAIN FACADE, THERE IS A FINISHING MOLDING WHICH WILL BE REPAIRED AND WILL BE THE SAME NOTHING WILL CHANGE. **Whith Galvanized Sheet No. 1**
(**Anexo SPECS Sheet**)

2.-ON MAIN FAÇADE THERE ARE PREVIOUSLY SIX WINDOWS AND ONE MORE IN THE CENTER THAT ON THE OUTSIDE WILL LOOK LIKE A DOOR BUT, ON THE INSIDE IT WILL CONTINUE TO BE A WINDOW, BECAUSE IT IS HIHER AS SHOWN IN THE PHOTO OF THE PROPOSED RENDER.

(The Window measurements will not be altered, they will be the same, in 1st. & 2nd. Level, Complying with the City Requirements)(Material Frame & Insulated Glass) (**See Plan HD A**)

3.- IN FRONT, First Floor PROPOSED Double Door Iron Gate, (**See Plan HD A**)

