

							South Texas Auto Rebuilders,	
							Total Price	\$403.00
Line #	Description	Mfgr	Mfgno	QTY	UOM	Estimated	Unit	Extended
1	Section I:Air conditioning system repairs for r			1	PKG		\$403.00	\$403.00
1.1	Standard Shop Labor Rate			1	Hourly Labo		\$100.00	
1.2	FieldLabor Rate			1	Hourly Labo		\$100.00	
1.3	Diagnostic ShopLabor Rate			1	Hourly Labo		\$100.00	
1.4	DiagnosticFieldLabor Rate			1	Hourly Labo		\$100.00	
1.5	Percent of Discount offered.			1	Percentage		10.0%	
1.6	Repairs will be completed within how many \			1	Working Da		\$3.00	