4282 I H 10 East San Antonio, TX 78219 Bexar

Voice: 210-333-1881 Fax: 210-333-1878

To:

# REPAIR ORDER

Repair Order Number: 20430

Repair Order Date: Feb 25, 2025

Page:

1

#### Ship To:

CITY OF LAREDO 1102 BOB BULLOCK LOOP LAREDO, TX 78043 USA CITY OF LAREDO 1102 BOB BULLOCK LOOP LAREDO, TX 78043 USA

Customer ID	PO Number	Sales Rep Name
CITY OF LAREDO	UNIT# 9107	
Customer Contact	Mileage	Payment Terms
	Courier	Net 30th of Next Month

Quantity	Item	Description	Unit Price	Amount
1.00	2019 RA	M, MODEL - 4500, UNIT# 9107, VIN#	sept any (massing balonger 2 sept	
	3C7WRI	CL0KG646674		
1.00	REPAIR	PER CUSTOMERS INSTRUCTIONS	43,000.00	43,000.00
1.00	SHOP S	UPPLIES	300.00	300.00
1.00	PAINT S	UPPLIES	2,800.00	2,800.00
1.00	HAZARI	OOUS WASTE	163.10	163.10
1.00	305703,	BRKT D1 RH FRT	354.85	354.85
1.00	305705,	BRKT D1 RH REAR	360.73	360.73
1.00	305706,	BRKT D1 LH FRT	354.85	354.85
1.00	305709,	BRKT D1 LH REAR	360.73	360.73
8.00	197550,	SPACER RUBBER	5.58	44.64
1.00	305711,	STONE GUARD NO DROP	215.03	215.03
1.00	305712,	DOOR SILL SS #8 COMPARTMENT	135.13	135.13
10.00	013893,	GASKET DOOR BULB	5.74	57.40
10.00	013385,	188X.50 ADHESIVE GASKET	1.63	16.30
1.00	305713,	WINDOW 18X18 SLIDE	572.23	572.23
6.00	305715.	GASKET 12X12	6.56	39.36
1.00	305716,	L BAR RH ANTIMC	495.85	495.85

I hereby authorize the repair work to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. You not responsible for loss or damage to the vehicle, components or contents due to collisions n your negligence, or due to fire, theft or other casualty regardless of whether or not such fire, to other casualty is due to your negligence; and you and your agents are hereby released from and all claims for such loss and damage. I am the person or agent acting on behalf of the perwho is obligated to pay for the repairs of this vehicle. I understand that this vehicle is subject repossession if payment is stopped or dishonored for any reason in accordance with 9.503 or Texas Business and a Commerce Code. I understand that if collection procedures are implimed to secure payment, my final invoice will be increased by a minimum of 35% to cover collectic and if I am sued for collection, I will be responsible for any and all legal fees incurred by Collic Country Repair.

Subtotal	Continued
Sales Tax	Continued
Freight	Continued
TOTAL	Continued

4282 I H 10 East San Antonio, TX 78219 Bexar

Voice: 210-333-1881 Fax: 210-333-1878

# REPAIR ORDER

Repair Order Number: 20430

Repair Order Date: Feb 25, 2025

Page:

2

Sales Rep Name

#### Ship To:

CITY OF LAREDO 1102 BOB BULLOCK LOOP LAREDO, TX 78043 USA

To:		
1102 BO	LAREDO B BULLOCK LOOP , TX 78043	

**Customer ID** 

nt Terms	Payment	UNIT# 9107 Mileage	CITY OF LAREDO  Customer Contact	
	Net 30th of N	Courier		
Amount	Unit Price	Description	ntity Item	
16.3	1.63	013385, 188X.50 ADHESIVE GASKET	10.00	
197.38	197.38	013505, HNDLE INSIDE LCB CNNC REAR	1.00	
427.68	427.68	013749, HANDLE LH LGB CNNC REAR	1.00	
286.18	143.09	013495, BEZEL KIT TRIMARK HNDL	2.00	
546.38	546.38	305717, STEPWELL ASSY STD RR	1.00	
207.98	207.98	305720, B REAR THRESHOLD CHAMFED	1.00	
56.4	4.70	305741, SAFETY WALK 3 IN W GRIT	12.00	
695.60	695.60	013377, SUPER HOOP STEP	1.00	
358.3 <sup>-</sup>	358.31	229421, LITE FLASHING RED LED	1.00	
28.88	28.88	229420, FLANGE OPT CHRM PLATED	1.00	
212.4	212.41	305739, GRAB RAIL ANTMC	1.00	
70.50	70.50	305740, ALUM COVE ANOD 1/2 IN	1.00	
2,662.66	121.03	013888, CRASH RAIL EXTRU	22.00	
129.26	64.63	013281, BK CRASH RAIL INSERT	2.00	
109.06	5.74	013655, PIN STRIPE 3/8 WHT	19.00	
19.56	1.63	013473, SPACER NYLON STAND OFF	12.00	
19.64	4.91	013745, UNISTRUT NUT	4.00	
244.40	122.20	013854, RUBBER RUB RAIL PLATE 94	2.00	

PO Number

I hereby authorize the repair work to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. You not responsible for loss or damage to the vehicle, components or contents due to collisions n your negligence, or due to fire, theft or other casualty regardless of whether or not such fire, to ther casualty is due to your negligence; and you and your agents are hereby released from and all claims for such loss and damage. I am the person or agent acting on behalf of the per who is obligated to pay for the repairs of this vehicle. I understand that this vehicle is subject repossession if payment is stopped or dishonored for any reason in accordance with 9.503 or Texas Business and a Commerce Code. I understand that if collection procedures are implimed to secure payment, my final invoice will be increased by a minimum of 35% to cover collectic and if I am sued for collection, I will be responsible for any and all legal fees incurred by Collic Country Repair.

Subtotal	Continued
Sales Tax	Continued
Freight	Continued
TOTAL	Continued

4282 I H 10 East San Antonio, TX 78219 Bexar

Voice: 210-333-1881 Fax: 210-333-1878

# REPAIR ORDER

Repair Order Number: 20430

Repair Order Date: Feb 25, 2025

Page:

3

Sales Rep Name

#### Ship To:

CITY OF LAREDO 1102 BOB BULLOCK LOOP LAREDO, TX 78043 USA

To:	Ī
CITY OF LAREDO 1102 BOB BULLOCK LOOP LAREDO, TX 78043 USA	

**Customer ID** 

Oud to morning	1 O Namper	Sales N	ep wante
CITY OF LAREDO	UNIT# 9107		
Customer Contact	Mileage	Payment Terms	
	Courier	Net 30th of	Next Month
Quantity Item	Description	Unit Price	Amount
1.00	013940, FENDER RING WHEEL WELL SUPT	197.40	197.40
1.00	013608, FENDER RING INSERT W DRP 19	128.08	128.08
1.00	013855, RUBBER WW RING PLATE 94	141.00	141.00
1.00	305696, RUNNING BOARD RH RR	1,150.33	1,150.33
1.00	305702, RUNNING BOARD LH RR	1,150.33	1,150.33
1.00	AST63114125, 1 1/4 X 1 1/4 X .125 ALUM SQ TUBE	52.50	52.50
	12FT		
1.00	AST612250, 2 X 2 X 1/4 ALUM SQ TUBE 12FT	150.00	150.00
1.00	AST632125, 2 X 2 X .125 ALUM SQ TUBE 12FT	83.75	83.75
1.00	AST631125, 1 X 1 X .125 ALUM SQ TUBE 12FT	38.75	38.75
1.00	AST63114125, 1 1/4 X 1 1/4 X .125 ALUM SQ TUBE	52.50	52.50
	12FT		
1.00	AFL61382, 3/8 X2 ALUMINUM FLAT	80.96	80.96
1.00	AAN612214, 2X2X1/4 ALUMINUM ANGLE	110.39	110.39
2.00	ASH52125PVC, .125" ALUMINUM SHEET 4X10	420.65	841.30
1.00	68534364AA, DOOR FRT	513.00	513.00
1.00	5182440AA, NAMEPLATE REAR	87.15	87.15
1.00	SSSH4142, 14GA (075) SS SHEET	493.75	493.75

**PO Number** 

I hereby authorize the repair work to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. You not responsible for loss or damage to the vehicle, components or contents due to collisions n your negligence, or due to fire, theft or other casualty regardless of whether or not such fire, to other casualty is due to your negligence; and you and your agents are hereby released from and all claims for such loss and damage. I am the person or agent acting on behalf of the perwho is obligated to pay for the repairs of this vehicle. I understand that this vehicle is subject repossession if payment is stopped or dishonored for any reason in accordance with 9.503 or Texas Business and a Commerce Code. I understand that if collection procedures are implimed to secure payment, my final invoice will be increased by a minimum of 35% to cover collectic and if I am sued for collection, I will be responsible for any and all legal fees incurred by Collic Country Repair.

Subtotal	Continued
Sales Tax	Continued
Freight	Continued
TOTAL	Continued

4282 | H 10 East San Antonio, TX 78219 Bexar

Voice: 210-333-1881 Fax: 210-333-1878

## REPAIR ORDER

Repair Order Number: 20430

Repair Order Date: Feb 25, 2025

Page:

4

#### To:

CITY OF LAREDO 1102 BOB BULLOCK LOOP LAREDO, TX 78043 USA

## Ship To:

CITY OF LAREDO 1102 BOB BULLOCK LOOP LAREDO, TX 78043 USA

Customer ID	PO Number	Sales Rep Name
CITY OF LAREDO	UNIT# 9107	
Customer Contact	Mileage	Payment Terms
	Courier	Net 30th of Next Month

Quantity	Item	Description	Unit Price	Amount
2.00		013932, CRASH RAIL END CAP	29.38	58.76
1.00		10495940, EBERHARD HANDLE GASKET	17.25	17.25
1.00		10322209, WNDW FRAME 18	52.88	52.88
1.00		FREIGHT	326.10	326.10
1.00		10X2 1/2 PPSMS SCREW 50PK	12.33	12.33
1.00		10-24 X 2 1/2 OPMS SCREW 20PK	9.26	9.26
2.00		197582, STRIKER BOLT	32.88	65.76
1.00		197589, HANDLE ECMC1	489.50	489.50
1.00		AAN6311116, 1X1X1/16 ANGLE ALUMINUM	22.50	22.50
1.00		AAN63343418, 3/4X3/4X1/8 ANGLE ALUMINUM	30.00	30.00
36.00		013891, GASKET DOOR SEAL	3.26	117.36
1.00		HD GRAPHICS INV#643344 DECALS	2,348.75	2,348.75
1.00		6MS38GXHAA, EXT WHEEL HOUSE	42.25	42.25
				7

I hereby authorize the repair work to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. You not responsible for loss or damage to the vehicle, components or contents due to collisions n your negligence, or due to fire, theft or other casualty regardless of whether or not such fire, to other casualty is due to your negligence; and you and your agents are hereby released from and all claims for such loss and damage. I am the person or agent acting on behalf of the per who is obligated to pay for the repairs of this vehicle. I understand that this vehicle is subject repossession if payment is stopped or dishonored for any reason in accordance with 9.503 or Texas Business and a Commerce Code. I understand that if collection procedures are implimed to secure payment, my final invoice will be increased by a minimum of 35% to cover collection and if I am sued for collection, I will be responsible for any and all legal fees incurred by Collic Country Repair.

Subtotal	64,422.67
Sales Tax	1,767.37
Freight	0.00
TOTAL	66,190.04